

BELZONA SUPERWRAP ALLOWS DRILLING TO CONTINUE

ID: 7630



PROBLEM

Due to long lead time fabricating new sections of pipe, Belzona SuperWrap was used to reinstate the required strength to keep the high pressure lines in operation for at least 1 year.

APPLICATION SITUATION

A platform off the coast of Baku had to stop drilling due to wall loss on the HP mud lines. The problem areas were on 3 bend sections.

APPLICATION METHOD

As per Belzona SuperWrap training

BELZONA FACTS

Drilling needed to commence immediately and due to long lead time to replace the pipe sections, Belzona SuperWrap was able to give the required up time.

INDUSTRY

Oil & Gas

LOCATION

Azerbaijan

APPLICATION DATE

November 2017

PRODUCTS

Belzona SuperWrap II

SUBSTRATE

ASTM A 519 Gr 4130

PHOTOS

1. View of Pipe before 21 wraps
2. View of Pipe before 12 wraps
3. View of SuperWrap repair: 21 wraps
4. View of SuperWrap repair: 12 wraps

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

