

4311 COATS A SULFURIC ACID TANK AT A CHEMICAL PLANT

ID: 7648



PROBLEM

Chemical attack onto the metal was taking a toll. The area was hard to shut down due to the need for this product during production.

APPLICATION SITUATION

The customer wanted to coat a previously uncoated Sulfuric Acid tank.

APPLICATION METHOD

The contractor used a heated plural component pump to do the application as per Belzona's spray instructions. The application was done in accordance to Belzona system leaflet TCC-5.

BELZONA FACTS

The Engineer had used Belzona at another plant and wanted to use Belzona for this application.

INDUSTRY

General Industry

LOCATION

Northern Florida

APPLICATION DATE

October 2017

PRODUCTS

Belzona 4311 (Magma CR1)

SUBSTRATE

Carbon steel.

PHOTOS

1. This is the tank after blasting with Black Beauty to get the required Belzona cleanliness standard.
2. This shows the pump they used.
3. The spray team about to start.
4. Finished application of 4311.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

