

BELZONA REPAIRS VULCANIZED RUBBER LINED PUMP

ID: 765



PROBLEM

A large area of the rubber had been eroded away.

APPLICATION SITUATION

Vulcanized rubber lined pump body

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet SHM-11.

BELZONA FACTS

Belzona Elastomer outlasted the original rubber and allowed localized repairs to be carried out on site without having to return the pump for re-vulcanizing.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical Plant, Italy

APPLICATION DATE

April 2006

PRODUCTS

Belzona 2111 (D&A Hi-Build Elastomer)

SUBSTRATE

Vulcanized rubber

PHOTOS

1. Pump body before application
2. Close up of damaged rubber
3. Upper body after application
4. Lower body after application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

