

BELZONA PROVIDES A BULK REPAIR TO A MEAT FREEZER FLOOR

ID: 7662



PROBLEM

Freezer floors have been under 24/7 heavy forklift operation and freezing conditions for more than 40 years. Some areas needed major overhaul. Major concrete damage was found on floors that are indispensable for plant operation. In addition, some localized repairs were needed all over the place. Turnaround time was also an issue with only 3 days to perform repairs.

APPLICATION SITUATION

Freezer floors.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona System Leaflet FPA-1. A slurry mix of Belzona 4154 was used to create a foundation where dirt was the substrate. Belzona 4124 was applied over to minimize the cost of deep pour. Belzona 4111 was used as a top layer because of its unique properties.

BELZONA FACTS

Backed by over 65 years of experience, Belzona was able to specify the appropriate materials. Belzona was chosen over a new concrete pour due to previous performance at the plant and time constraints. Belzona was able to deliver a high performance and a fully cured floor system.

INDUSTRY

Food & Drink

LOCATION

Meat Processing Plant, Florida, USA

APPLICATION DATE

December, 2017

PRODUCTS

Belzona 4154 (Bulkfill Resin) mixed with pea gravel
Belzona 4124 (Bulkfill)
Belzona 4111 (Magma-Quartz)
Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

40 year old concrete

PHOTOS

1. Condition of the floor after removing covering metal plates
2. Surface preparation on the way
3. Ongoing application (Belzona 4154 and pea-gravel)
4. Finished repair after Belzona 4111 application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

