

BELZONA SPRUCES UP WHILE REPAIRS AND PROTECTS AN AIRPORT FOUNTAIN

ID: 7666



PROBLEM

Old marine paint used for the inside of the display fountain was a dull color and difficult to keep clean.

APPLICATION SITUATION

Fountain outside one of the terminals.

APPLICATION METHOD

The surface was prepared by scarifying concrete. Belzona 5233 (Clear) was applied to the rock face around the outside of the fountain. Some cracks were fixed by applying Belzona 4124. The inside of the fountain was coated with Belzona 5812DW (Blue).

BELZONA FACTS

The Customer wanted a blue coating for the inside of the fountain that would be easy to clean and would last under immersion. They also wanted the rock face on the side to be sealed with Belzona 5233 (Clear) and any cracks in the rock face were filled with Belzona 4124. The Customer wanted to use Belzona products due to the successful previous applications with the other fountains at this facility.

INDUSTRY

LOCATION

International Airport, Florida, USA

APPLICATION DATE

Summer 2017

PRODUCTS

Belzona 5812DW (Blue)
Belzona 4124 (Bulkfill)
Belzona 5233 (Clear)

SUBSTRATE

Concrete

PHOTOS

1. Containment for the fountain to keep concrete dust away from the adjacent rental cars.
2. Scarifying the inside of the fountain
3. Applying Belzona 5233 clear
4. Finished application and fountain started 3 days after application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

