

# BELZONA GRANOGRIP SYSTEM PROVIDES SAFETY AT A MEDICAL FACILITY

ID: 7670



## PROBLEM

Determining that the open grates would be a safety hazard and untreated steel would be a slip hazard the engineers called Belzona for a solution. Samples were sent to the building inspector and he chose Belzona 4411 GranoGrip with Belzona 9211 Aggregate.

## APPLICATION SITUATION

New construction of a medical facility. The plans called for open grates over the sidewalk drains. The building inspector rejected the open grates as a safety hazard, especially for high heel shoes.

## APPLICATION METHOD

The 12 - 1' x 3' plates were grit blasted in the shop. Belzona 4411 was brush applied and Belzona 9211 pressed in over the whole surface.

## BELZONA FACTS

Belzona has assisted the medical facility in providing patients and visitors with a safe entry that visually meets the high standards of the development.

## INDUSTRY

## LOCATION

Medical Facility, Washington, USA

## APPLICATION DATE

November, 2017

## PRODUCTS

Belzona 4411 (GranoGrip)

Belzona 9211 (Supergrip Aggregate)

## SUBSTRATE

Steel

## PHOTOS

1. Open grate - safety hazard.

2. Twelve steel plates after being grit blasted in a machine shop.

3. & 4. Sidewalk drain covers in place.

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

