

BELZONA KEEPS US NAVY FIRE PUMP READY TO RUN

ID: 7675



PROBLEM

Due to lack of frequent use, this fire pump onboard a US Navy ship sits for extended amounts of time with sea water inside of it causing severe corrosion. This makes the fire pump potentially unreliable in case of an emergency.

APPLICATION SITUATION

Fire pump impeller on-board a US Navy ship.

APPLICATION METHOD

Grit blasted to achieve a 3-5 mil profile, and coated with Belzona 1111 to fill in and rebuild the pitting and damage to a smooth clean finish. Allowed to firm up, and then overcoated with the first coat of Belzona 1341. The impeller wear ring was also heavily corroded and was machined down to a rough thread pattern and overbuilt with Belzona 1111 at this time. While waiting for the wear ring application to solidify, the second coat of Belzona 1341 was applied. Finally, the wear ring surface was machined back to the original specifications.

BELZONA FACTS

This impeller would have had to be replaced, but with Belzona materials being used, repairing it only cost a couple hundred US dollars without risking heat distortion by welding on it. The added bonus is an increase in efficiency whenever the pump is operated.

INDUSTRY

Marine

LOCATION

Washington, USA

APPLICATION DATE

February 2017

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Brass

PHOTOS

1. Original condition of the impeller.
2. Belzona 1111 applied to rebuild the damage. First coat of Belzona 1341 applied
3. Belzona 1111 rebuilding the wear rings.
4. Completed application, ready for re-assembly.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA