

BELZONA RESTORES ROPE GUIDES

ID: 7682



PROBLEM

The ship had severe pitting marks and corrosion on the rope guides. This meant ropes could be damaged when sliding over the surface.

APPLICATION SITUATION

Bunkering Ship used to refuel various ships entering and leaving the Cape Town port. The ship spends most of its time moored in the harbor.

APPLICATION METHOD

Application was carried out in accordance with Belzona system leaflet SOS-02.

BELZONA FACTS

The customer required a fast and easy solution to avoid an extremely costly replacement. These parts are extremely difficult to source and it is likely it would have required manufacturing a new one. The Belzona solution avoided this and was completed within two days.

INDUSTRY

Marine

LOCATION

Cape Town, South Africa

APPLICATION DATE

February 2018

PRODUCTS

Belzona 1111 (Supermetal)

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Mild steel

PHOTOS

1. Potentially damaged ropes
2. Rope guide
3. Application in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

