




BELZONA COMPOSITE FERRY WRAP

ID: 7698



PROBLEM

Suffering from external corrosion

APPLICATION SITUATION

Ferry Pipe

APPLICATION METHOD

The application was carried out in accordance with Belzona system leaflet VPF-11. This was followed by over-coating with Belzona 5821.

BELZONA FACTS

The customer required a solution that was quick in order to get back into service.

INDUSTRY

Transport

LOCATION

France

APPLICATION DATE

November 2017

PRODUCTS

Belzona 1121 (Super XL-Metal)
Belzona 5821

SUBSTRATE

Mild Steel

PHOTOS

1. Damaged pipe
2. Belzona 1121 wrap in progress
3. Composite Wrap complete
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

