

BELZONA UPGRADES TANK FARM FLOOR

ID: 774



PROBLEM

Thin top layer of concrete delaminated allowing Bacteria growth and unacceptable appearance.

APPLICATION SITUATION

Floor area around storage tanks

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet FPA-1

BELZONA FACTS

A long history of successful applications gave the customer confidence that this was the only practical solution.

INDUSTRY

Buildings & Structures

LOCATION

AFB Pet Food Additive Manufacturer, OFallon, MO

APPLICATION DATE

April 2006

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete

PHOTOS

1. Old concrete
2. Start of application
3. Finished job

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

