


A SHOWER AT A MINE MADE SAFE WITH BELZONA

ID: 7756



PROBLEM

Originally, the floor was tiled. Eventually, it was damaged and an epoxy coating was used. It did not last too long before it began to flake off.

APPLICATION SITUATION

A shower room at a live-in camp at a mine in Alaska.

APPLICATION METHOD

The application was carried out in accordance with a modified version of FPA-1 System Leaflet. The entire floor was prepped with a concrete grinder. The existing epoxy was removed, and the surface of the concrete was smoothed off leaving clean fresh concrete. Belzona 4911 and 4111 were applied over the entire floor to smooth off the irregularities and fill in the damage that was present from where the grout lines were with the original tile. Once that was completed, Belzona 5911 was applied with a semi-fine alumina oxide aggregate to provide a safe slip-free floor. Following the Manufacturer's Instructions For Use, Belzona 5111 was applied in two coats, first white, then gray as the Customer chose.

BELZONA FACTS

This mine location and Belzona have had a good history together, so when the shower floor needed to be addressed, they called Belzona. After much consideration and careful evaluation of the cleaning products being used, we were, with the technical help of TKL at Belzona Global. The order was placed and shipped and a full set of instructions were written and sent to the customer along with all of the Instructions For Use for each material. The customer then undertook the application with his team. It took them a total of 3 days from start to finish, and they were very pleased with the results, and will be doing their other shower soon. That is one of the benefits of Belzona products, they are simple and safe enough for an in-house maintenance team to use without prior experience.

INDUSTRY

Mining & Quarrying

LOCATION

Alaska, USA

APPLICATION DATE

March 2018

PRODUCTS

Belzona 4911 (Magma TX Conditioner)
Belzona 4111 (Magma-Quartz)
Belzona 5911 (Ceramic Conditioner)
Belzona 5111 (Ceramic Cladding)

SUBSTRATE

Concrete

PHOTOS

1. Shower in original condition.
2. Shower in original condition.
3. Application is complete.
4. Application is complete.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

