

BELZONA REPAIRS AND PROTECTS GAS STATION CONCRETE FLOOR

ID: 7761



PROBLEM

The concrete floor of this gas station was attacked by gas and needed to be resurfaced and protected. Because it can easily get slippery it also needed a slip-resistant system.

APPLICATION SITUATION

The concrete floor of this gas station was damaged, greasy and slippery.

APPLICATION METHOD

The floor was steam cleaned then grit blasted. The concrete has then been resurfaced with Belzona 4151 and covered with Silica 0.5-1.25 using Belzona Know-How system leaflet FPA-8. 4 hours later, Belzona 5811 was applied on top of the silica to complete the non-slip system and protect the surface from hydrocarbons.

BELZONA FACTS

The customer is really satisfied by this rapid solution which looks very neat. He is also happy to have a system that will be resistant to hydrocarbons. Other competitors were contacted for this work, but they were not sure about the resistance of their system, so the customer preferred to go for Belzona.

INDUSTRY

Buildings & Structures

LOCATION

France

APPLICATION DATE

July 2018

PRODUCTS

Belzona 4151 (Magma-Quartz Resin)
Belzona 5811 (immersion grade)

SUBSTRATE

Concrete

PHOTOS

1- Damaged and slippery concrete 2- Grit blasted concrete 3- Resurfaced concrete with silica 4- Final result with Belzona 5811

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

