

BELZONA REPAIRS TANK LEG SUPPORTS AT A DISTILLERY

ID: 7772



PROBLEM

Several VAT tank leg supports were corroded due to the break down of the original paint system. Some tanks had already been condemned due to metal loss and through wall defects in the tank supports.

APPLICATION SITUATION

VAT tank leg supports at a distillery.

APPLICATION METHOD

The previous paint was removed by saturation blasting to keep the dust levels down on-site. The VAT legs were then coated by hand with Belzona 5811 in accordance with a modified version of Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

This system provides a long-term corrosion resistance and an aesthetically pleasing finish.

The application was re-visited 1 year later, and found to still be forming with no damage or repairs required.

INDUSTRY

Food & Drink

LOCATION

United Kingdom

APPLICATION DATE

2018

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

Damaged tank leg supports

Damaged tank leg supports

1st coat of Belzona 5811

Application after 1 year in service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

