


RESIDENTIAL ROOF REPAIRED BY BELZONA

ID: 7784



PROBLEM

Rain water was pooling and penetrating under the roofing tiles. Several attempts were made with silicon and mastic materials to address the problem.

APPLICATION SITUATION

A residential building had an extension retrofitted, however water was penetrating between the house and the new roofing area.

APPLICATION METHOD

Belzona 4141 was used to recontour the area subjected to pooling of water. Belzona 3111 was then applied between the wall of the house and the extension roofing tiles.

BELZONA FACTS

Several attempts were made to address the leaking but all failed or were unaesthetic.

INDUSTRY

Buildings & Structures

LOCATION

Thailand

APPLICATION DATE

October 2018

PRODUCTS

Belzona 4141 Magma Build
Belzona 3111 Flexible Membrane

SUBSTRATE

Roofing Tiles

PHOTOS

Picture 1 - The roofing area
Picture 2 - Rebuilding with Belzona 4141
Picture 3 - Application of Belzona 3111
Picture 4 - The completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.