


BELZONA PREVENTS WATER PENETRATION INTO A DATA STORAGE FACILITY

ID: 7786



PROBLEM

Spider cracks compromising the integrity of the staircase and allowing water to penetrate into the building's data center underground.

APPLICATION SITUATION

Steps at the entrance to a financial building.

APPLICATION METHOD

The entire repair was complete on a Saturday afternoon after employees vacated the building. The cracks were filled with Belzona 4111 and the entire surface was restored for waterproofing and a long-lasting protection.

BELZONA FACTS

As an alternative, the Customer considered replacing the steps, or use other coatings. Belzona was chosen as it offered minimal downtime, durability and experience with similar situations.

INDUSTRY

Commercial Facilities

LOCATION

Virginia, USA

APPLICATION DATE

July 2004

PRODUCTS

Belzona 4111(Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

Showing Damage After powerwashing
Completed application; the cracks filled,
and the steps re-surfaced with Belzona
4111 for a long-term protection

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.