


PAPER MILL PRESS ROLL SAVED FROM REPLACEMENT BY BELZONA

ID: 7823



PROBLEM

Trapped material under the press roll caused scoring damage to the surface.

APPLICATION SITUATION

Solids Handling Machinery - paper mill press roll.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona system leaflet SHM-9.

BELZONA FACTS

The only alternative was to replace the rollers entirely, as no hot work techniques could be used due to the geometry of the rollers. The cost and lead time of the Belzona repair is significantly lower than replacement, resulting in huge savings for the customer.

INDUSTRY

Pulp & Paper

LOCATION

Egypt

APPLICATION DATE

August 2018

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 9111 (Cleaner/Degreaser)

SUBSTRATE

Hard Rubber

PHOTOS

Damage to the roller.

Belzona used to rebuild the surface.

Mark up of areas to be drilled.

Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

