

WOOD PARTICLES DRUM REPAIRED WITH BELZONA

ID: 7824



PROBLEM

The glue and wood particles mixture was very abrasive and the after a short period of time, there was localised damage to the drum.

APPLICATION SITUATION

The customer needed to mix special glue with wood particles to achieve a uniform material for the production of boards.

APPLICATION METHOD

Application was carried out using Know-How System Leaflet SHM-13

BELZONA FACTS

The only alternative to the Belzona solution was to replace all of the drums with new ones, as welding was difficult and time consuming. Also, replacing would have been very expensive and time consuming. The Belzona solution solved these problems that the customer had faced.

INDUSTRY

General Industry

LOCATION

Slovakia

APPLICATION DATE

2009

PRODUCTS

Belzona 1812 (Ceramic Carbide FP)

SUBSTRATE

Steel

PHOTOS

1. Surface after blasting - ready for repair
2. Belzona 1812 local application
3. Perfect protection against abrasive mixture

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.