

PIPE ADAPTER REPAIRED BY BELZONA

ID: 7825



PROBLEM

Maize kernels transport is very abrasive. This product is able to damage some parts of the pipe system in 6 months.

APPLICATION SITUATION

This pipe system customer needs for maize kernels transport

APPLICATION METHOD

Application was carried out using Know-How System Leaflet SHM-13 with Belzona 9811.

BELZONA FACTS

Customer used to change some parts of pipe system before Belzona protection, but it was expensive and after 6 months was in the same situation. Then they tried to weld some steel protection against abrasion, but result was the same. Belzona solution solved these customer problems and they are satisfied with it.

INDUSTRY

Transport

LOCATION

Maize starch producer in Slovakia

APPLICATION DATE

2016

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1812 (Ceramic Carbide FP)
Belzona 9811 (Alumina Tiles)

SUBSTRATE

Steel

PHOTOS

1. Pipe system for maize kernels transportation
2. Pipe adaptor in system
3. Perfect protection against abrasive maize kernels
4. Detail of the finished repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

