



BELZONA GETS TO GRIPS WITH SAFETY AT AN INTERNATIONAL CONFERENCE CENTRE

ID: 786



PROBLEM

The finish on the tiles which made up the steps was a slip hazard when wet. In addition to this the steps were subjected to heavy foot traffic and misuse by skateboards, necessitating renovation to a condition reflecting the status of the International Conference Centre.

APPLICATION SITUATION

Main entrance steps of Conference Centre

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 and FPA-8.

BELZONA FACTS

The customer was extremely pleased with the aesthetic appearance of the application, which aside from meeting their safety needs, matched the Organisations Logo. After 6 years of arduous service Belzona is still providing excellent performance and the rough surface prevents damage from skateboarders.

INDUSTRY

Buildings & Structures

LOCATION

International Conference Centre-UK

APPLICATION DATE

June 2003

PRODUCTS

Belzona 4131 (Magma-Screed)
Belzona 4411 (Granogrip)
Belzona 9221 (Surefoot Aggregate)

SUBSTRATE

Ceramic tiles

PHOTOS

1. Original condition of the entrance steps.
2. Safety Grip areas masked off.
3. The finished application.
4. Application after 6 years of service.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

