

HOMELAND SECURITY RUSH JOB COMPLETED WITH BELZONA

ID: 788



PROBLEM

This job had to be completed the same day problem identified so that the boat could sail on time.

APPLICATION SITUATION

Two old shower stalls on the boat allowed water to seep behind the stall walls rusting a 24" x 4" hole in the deck & leaked water into the engine room. The bulkhead was rusting badly as well

APPLICATION METHOD

Belzona® 4111 applied in accordance with Belzona System Leaflet FPA-1 & the new shower base & sides installed in front of the repair while the material was still wet.

BELZONA FACTS

The expensive alternative was to cut out a large chunk of deck plate & bulkhead and weld in new pieces. There was not enough time for this and the expense would have been high.

INDUSTRY

Military

LOCATION

U.S. Coast Guard

APPLICATION DATE

July 2006

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Steel deck & bulkhead

PHOTOS

1. The boat
2. One of two problem areas
3. Starting the repair
4. Completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

