

BELZONA REPAIR AN ENGINE CASING OF A LUXURY CAR

ID: 7882



PROBLEM

Several mounting bracket sets were cracked and broken. The customer wanted to achieve a perfect finish for both strength and aesthetic point of view. Belzona was chosen as an alternative to welding.

APPLICATION SITUATION

The engine casing was damaged due to a car crash.

APPLICATION METHOD

The application was carried in accordance with modified versions of Belzona Know-How System Leaflets ENC-1 and ENC-2.

BELZONA FACTS

The car manufacturer would not supply only a new engine casing, the cost of the new engine was €95,000. The cost savings from repairing with Belzona was nearly 100% of the alternative.

INDUSTRY

General Industry

LOCATION

Azerbaijan

APPLICATION DATE

October 2018

PRODUCTS

Belzona 1212

SUBSTRATE

Cast Aluminium

PHOTOS

1 - 3 Damaged engine mounting bracket sets

4. Completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.