


BELZONA OFFERS A PEACE OF MIND TO A PRIVATE VILLA OWNER

ID: 7886



PROBLEM

Poorly finished concrete walls and floors.

APPLICATION SITUATION

Five underground potable water storage tanks within a luxury villa.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-1, Belzona 4111 was used to repair the poorly finished concrete walls and floors of the tanks and Belzona 5891 was used to coat the internal surfaces of the tanks.

BELZONA FACTS

The customer was satisfied with both the product finish and the way the repair and coating were carried out. After the initial cleaning the water was crystal clear and odourless. The tanks were opened after a 1 year in service for cleaning and the coatings were found sound and intact.

INDUSTRY

Buildings & Structures

LOCATION

Saudi Arabia

APPLICATION DATE

2017

PRODUCTS

Belzona 4111 (Magma Quartz)

Belzona 5891 (HT Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. The potable water tank before the application.
2. Another view of a tank before the application.
3. Complete application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

