



BELZONA MATERIALS RECONDITION AIR CONDITIONER

ID: 79



PROBLEM

The tube sheet had suffered erosion/corrosion damage to the extent that three tubes no longer made contact with the sheet.

APPLICATION SITUATION

H.V.A.C. tube sheet repair

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Leaflet HEX-1.

BELZONA FACTS

The customers only alternative would have been to remove all the tubes and replace the sheet at a cost of \$33,000. The Belzona solution cost less than \$1,000.

INDUSTRY

General Industry

LOCATION

Property Management Company in South-Eastern U.S.A.

APPLICATION DATE

February 1995

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Steel and Copper

PHOTOS

1. Original condition of the tube sheet showing three tubes not in contact with the sheet
2. Tube sheet surface being prepared
3. The sheet, restored to full working order

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

