

BELZONA RESTORATION OF HISTORIC FEDERAL BUILDING

ID: 796



PROBLEM

The copper gutters had to be maintained watertight without replacement.

APPLICATION SITUATION

Copper gutters of historic site. Gutter system is part of the original structure and it is not permitted by the Federal Government to change materials.

APPLICATION METHOD

Application was carried out in accordance with Belzona System RPA-6. Power wire brushing and degreasing was carried out prior to application.

BELZONA FACTS

There was no way to replace the copper gutter system as dictated by the Federal Government. Alternatives such as silicone sealants would not provide required longevity. Belzona® 3111 was chosen due to the ability to coat the copper gutter system and maintain its functionality without removal. It maintained appearance to the satisfaction of the engineers.

INDUSTRY

General Industry

LOCATION

Pensacola, Florida

APPLICATION DATE

September 2006

PRODUCTS

Belzona 3111 (Flexible Membrane) fully reinforced system

SUBSTRATE

Copper

PHOTOS

1. Belzona 3111 being applied
2. Belzona initially applied to gutter seams
3. View of the finished gutter system coated with Belzona 3111
4. Another view of the finished gutter system coated with Belzona 3111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

