

BELZONA APPLIES ANTI-SLIP SYSTEM TO WOODEN MEZZANINE FLOOR

ID: 7963



PROBLEM

A resin-compacted chipboard floor was the substrate which needed repair. 200Kg tote trolleys were trafficked across this, wearing away the original coating and substrate of the mezzanine floor. The client tried 4 other coatings companies before trialing with Belzona.

APPLICATION SITUATION

A large distribution warehouse uses a mezzanine floor area for picking and the movement of tote trolleys.

APPLICATION METHOD

5231 was applied to a small patch, along with pull-off dollies as a small trial area. These showed adhesion approaching 850 psi. From this result, a larger trial was organised. Preparation was completed using large floor sanders and vacuums, followed by the application of the Belzona 5231 in accordance with Belzona system leaflet FPA-8.

BELZONA FACTS

All other trials failed and the only alternative seemed to replace the floor. The cost was huge as the mezzanine floor carried services under which also would have had to be moved and managed during the replacement. A coating was the only viable choice. Belzona 5231 was the only coating to perform.

The trial has been in place since the beginning of 2019, and has proven a suitable solution, outperforming the expected standards.

INDUSTRY

Commercial Facilities

LOCATION

Distribution Center, Worksop, UK

APPLICATION DATE

2019

PRODUCTS

Belzona 5231 (SG Laminate)

SUBSTRATE

Resin-compacted chipboard

PHOTOS

1. Small trial area
2. Dolly pull-offs in place
3. Applying 2nd Coat
4. Trial completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

