


# BELZONA SEALS HOTEL POOL DECK

ID: 798



## PROBLEM

The Plaza had severe hurricane damage and needed major repair. Among the needed repairs was the entire pool deck located on the second floor of the hotel.

## APPLICATION SITUATION

Pool Deck leaking water down into the hotel kitchen and maintenance area.

## APPLICATION METHOD

Belzona® 4111 applied to deck after careful preparation including levelling with a grinder. The drain covers were prepared and set in place with Belzona® 4111. Belzona® 3121 was used to seal stress cuts in the pad after they were cleaned, dried and prepared with a concrete grinder.

## BELZONA FACTS

The pool deck had been a serious issue for several years. Caulking, conventional concrete repairs and patching had taken place and could not hold up to time or poor weather. This along with guest traffic (pulling chairs over the surface, dragging boxes, etc) caused the owners to search for a better, more permanent solution. The finished pool deck was published on the front page of the Pensacola Journal.

## INDUSTRY

Buildings & Structures

## LOCATION

Hotel, Pensacola Florida

## APPLICATION DATE

September, 2001

## PRODUCTS

Belzona 4111 (Magma Quartz)  
Belzona 3121 (MR7)

## SUBSTRATE

Concrete

## PHOTOS

1. Stress cuts in concrete
2. Belzona 4111 with drain in place
3. Finished drain area
4. Finished pool deck

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured  
under an ISO 9001 Registered  
Quality Management System.

[www.belzona.com](http://www.belzona.com)

