


BELZONA REPAIRS CONDUCTOR CASING ON OFFSHORE PLATFORM

ID: 8045



PROBLEM

The cavity between the well head and conductor casing corrodes, vibrates, and becomes misaligned. The engineers performed an analysis that showed very high concentrated stress levels and loads acting on the cavity.

APPLICATION SITUATION

Conductor casing on an offshore platform.

APPLICATION METHOD

Belzona 7111 was poured to fill the void and was then sealed with Belzona 3411.

BELZONA FACTS

Belzona 7111 has excellent flow characteristics which meant the void was easily filled. This saved the customer time and money as the application was completed in 1 day.

INDUSTRY

Oil & Gas

LOCATION

Malaysia

APPLICATION DATE

December 2018

PRODUCTS

Belzona 7111

Belzona 3411 (Encapsulating Membrane)

SUBSTRATE

Wellhead conductor and casing - carbon steel

PHOTOS

Surface preparation by blasting

Pouring Belzona 7111

Sealing with Belzona 3411

Finished Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.