

BELZONA HELPS IN THE PROTECTION OF A SURFACE UNDER THE GRANULE SCRAPER.

ID: 8060



PROBLEM

Corrosion of concrete and surface due to the scraper moving the granules around the area.

APPLICATION SITUATION

Modernisation and protection of the surface area under the granule scraper.

APPLICATION METHOD

Repair any surface damaged concrete areas with Belzona 4151 Sealing the surface under the scraper using Belzona 5811.

BELZONA FACTS

Long-lasting chemical resistance with Belzona 5811 securing the surface under the scraper.

INDUSTRY

General Industry

LOCATION

Puławy, Poland

APPLICATION DATE

2019

PRODUCTS

Belzona 4151 (Magma Quartz Resin)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Application Area Picture
2. Area to be treated under the scraper
3. Applying Belzona 4151 & Belzona 5811
4. Application Completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

