


CORROSION PROTECTION 2 X INDUSTRIAL STORAGE TANKS WITH BELZONA 5811

ID: 8073



PROBLEM

Corrosion on the internal linings of two large storage tanks at a large industrial plant in Poland.

APPLICATION SITUATION

Corrosion protection for 2 DEMI water tanks (Total area - 1520 m², 2000m³)

APPLICATION METHOD

The application of Belzona 5811 was completed in accordance with Belzona System Leaflet TCC-5.

BELZONA FACTS

Long-term protection against corrosion on the tanks.

INDUSTRY

Water / Wastewater

LOCATION

Poland

APPLICATION DATE

2019

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

1. One of the storage tanks to be coated.
2. Belzona 5811 applied internally.
3. Testing dry film thickness.
4. Application complete on the internal lining.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

