

BELZONA SECURES A LIFTING WINCH

ID: 8075



PROBLEM

Chocking of heavy machinery winch.

APPLICATION SITUATION

Lifting winch being secured on the deck of a dredging vessel

APPLICATION METHOD

The installation was carried in accordance with Belzona System Leaflet GSS-12.

BELZONA FACTS

The 4 supporting pads were chocked using Belzona 7111 in order to ensure optimum load transmission as well as long term protection against vibration. The fast curing properties of the material were a key factor for the operator of the ship.

INDUSTRY

LOCATION

France

APPLICATION DATE

August 2017

PRODUCTS

Belzona 7111

SUBSTRATE

Steel

PHOTOS

1. Dredging vessel
2. Area marked and damned, ready for application
3. Pouring in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA®