


BELZONA 1321 IN USE AT A LARGE SAWMILL IN THE BALTICS

ID: 8093



PROBLEM

Worn lumber transfer rollers lack the required grip to transfer lumber quickly and efficiently. This inefficiency affected the ability of transferring lumber from one part of the plant to another, which was affecting revenue and production levels.

APPLICATION SITUATION

Grip Rollers in Lumber Mill were worn causing inefficient transfer of lumber system.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet SHM-12

BELZONA FACTS

These rolls are typically in service 1-2 years depending on the sawmill activity and type of lumber produced

INDUSTRY

General Industry

LOCATION

Estonia

APPLICATION DATE

2018

PRODUCTS

Belzona 1321 (Ceramic S- Metal)
Belzona 9211 (Supergrip Aggregate)

SUBSTRATE

Mild steel

PHOTOS

1. Rolls grip system worn smooth
2. Application of Belzona 1321 and Belzona 9211

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

