

BELZONA PROVIDES BONDING SOLUTION FOR TANK STAIRS

ID: 8100



PROBLEM

Stairs on the side of the tank suffering from severe galvanic corrosion, deeming the stairs unsafe to use.

APPLICATION SITUATION

Bonding stairs to the side of a tank as an alternative to welding.

APPLICATION METHOD

This application was carried out using a modified version of system leaflet VPF-15. The stairs were power washed and chiseled down to get rid of any loose contaminants. Once the stairs were cleaned the side of the tank and the bonding side of the stairs were grit blasted to Sa 2.5 before Belzona 1161 was used to bond the two surfaces together. Belzona 9341 was also incorporated into the paste grade for added support. Once the Belzona 1161 had cured a final coat of Belzona 5811 was applied for added corrosion resistance.

BELZONA FACTS

Welding wasn't an option in this circumstance as the tank would have had to be drained resulting in a loss of resources and also significant downtime. The Belzona solution was cold applied and therefore the tank didn't need draining.

INDUSTRY

Oil & Gas

LOCATION

Italy

APPLICATION DATE

2018

PRODUCTS

Belzona 1161 (Super UW-Metal)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

1. Overview of tank stairs
2. Severe galvanic corrosion
3. Belzona 1161 bonding the stairs to the tank
4. Finished application with a coating of Belzona 5811

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

