

BELZONA REBUILDS LARGE MOTOR BEARING HOUSING

ID: 811



PROBLEM

Bearing housing damaged due to mechanical failure.

APPLICATION SITUATION

Electric motor bearing housing.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-6.

BELZONA FACTS

Belzona solved the problem simply without the need for welding or any heat so avoiding distortion.

INDUSTRY

Power

LOCATION

Power station - Egypt

APPLICATION DATE

November 2005

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. General view of the worn bearing housing
2. Applying Belzona 1111 to rebuild the housing
3. Checking the dimensions after machining
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

