

WATERPROOFING COVERED LABORATORY BUILDING WITH BELZONA SYSTEM 3111

ID: 8113



PROBLEM

The deterioration of the asphalt lining in some areas were applied on the concrete roof of the laboratory roof, facilitated the entry of water into the offices and test offices, spoiling highly expensive measuring and testing equipment.

APPLICATION SITUATION

Flat cover of the main laboratory building within the thermal centre of As Pontes-Galicia

APPLICATION METHOD

The application was completed in accordance with Belzona System Leaflet RPA-6 and TCC-4.

BELZONA FACTS

The asphalt roof 600 m2 was repaired with Belzona 3111 after repairing with Belzona 2211.

INDUSTRY

Buildings & Structures

LOCATION

Coal Thermal Center in AS Pontes-Galicia

APPLICATION DATE

September 2019

PRODUCTS

BELZONA 2911 (Elastomer QD Conditioner)
BELOZNA 2121 (D&A Hi-Coat Elastomer)
BELZONA 3911 (PSC Conditioner)
BELOZNA 3111 (Flexible Membrane)
BELZONA 9311 (Reinforcement Sheet)

SUBSTRATE

CONCRETE AND ASPHALT FABRIC

PHOTOS

1 - START STATUS

2 - CLEANING

3 - APPLICATION BELZONA 3111

4 - FINAL STATE WITH SECOND LAYER OF BELZONA 3111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

