

BELZONA PNEUMATIC RUBBER FENDER REPAIR

ID: 8115



PROBLEM

Fenders were wrapped with tyres & chains for additional protection, which damages the fender & it become worn & punctured. Hence they were in need of a full service or replacement.

APPLICATION SITUATION

The Aban offshore company sent a fender which was being used to protect rig platform legs & they had become worn and punctured over time.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-12. Surfaces were prepared using a MBX machine. After Conditioning the areas with 2921 were rebuilt with Belzona 2211 incorporating Belzona 9341 (Reinforcement Tape).

BELZONA FACTS

Instead of replacing the fender which is time and cost consuming process, Belzona provided a solution, reducing downtime and significantly reducing overall costs to the customer.

INDUSTRY

Oil & Gas

LOCATION

Aban Offshore Ltd. Navi Mumbai, India

APPLICATION DATE

October 2019

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 2921 (Elastomer GP Conditioner)
Belzona 9341 (Reinforcement Tape)

SUBSTRATE

Rubber

PHOTOS

1. Deflated Fender & Punctured Area
2. Surface Prepared & Conditioning
3. Application With 2211 & 9341
4. Finished Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

