

BELZONA RESURFACES DETERIORATED BIKE RACK AT UK COLLEGE FACILITY

ID: 8124



PROBLEM

The Facilities Management team at the college wanted to resurface the bike rack as it was causing a trip hazard for those using the area. Not only that, but they wanted to improve the aesthetics for the staff and visitors using the facility.

APPLICATION SITUATION

The bike rack at a UK college facility was showing significant signs of deterioration, with vast areas of the concrete surface spalled or cracked due to wear and weathering.

APPLICATION METHOD

The metal rack, which was bolted in the concrete, was removed and the surface was inspected for areas of crumbling and loose material. Any loose concrete was chiselled away, ensuring a solid surface. Next, the entire bike rack was pressure washed, removing any contaminants and plant growth. Once dry, Belzona 4911 was used to condition the concrete prior to the application of Belzona 4131. Working across in sections, the bike rack was resurfaced using a float to provide a smooth finish.

BELZONA FACTS

The Facilities Management team had a week available to carry out necessary repairs during the college's half-term break. The Belzona mortar repair systems were the ideal choice in this instance, being able to receive foot traffic after just a matter of days curing and providing a long-term solution to the issue.

INDUSTRY

Commercial Facilities

LOCATION

Yorkshire, UK

APPLICATION DATE

April 2019

PRODUCTS

Belzona 4131 (Magma Screed)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Bike rack showing large areas of spalled and deteriorated concrete
2. Application of Belzona 4131 (Magma Screed)
3. Resurfacing the final area of the bike rack
4. Revisited several weeks later and in perfect condition

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

