

SHOPPING CENTRE STEP WITH BELZONA GRIP SYSTEM

ID: 8128



PROBLEM

Limited closure times were available, any solution had to be fast back to service.

APPLICATION SITUATION

A set of stone steps leading to the entrance of a shopping centre was identified as a potential slip hazard in wet or icy conditions. A hard wearing, easy to see grip system was required to give positive traction to pedestrians using the steps.

APPLICATION METHOD

The step nosings were abraded with a floor grinder. The Belzona 4411 system was then applied by brush before the Belzona 9221 was sprinkled on top to form the grip system

BELZONA FACTS

The application was able to be carried out over one day so minimal disruption to the area was caused

INDUSTRY

Buildings & Structures

LOCATION

Paisley, Scotland

APPLICATION DATE

October 2018

PRODUCTS

Belzona 4411 Granogrip
Belzona 9221 Surefoot white

SUBSTRATE

Stone

PHOTOS

1. Close up of application
2. Top down view
3. Bottom view

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

