

BELZONA PROVIDES UNCONVENTIONAL TANK BASE SEALING

ID: 8131



PROBLEM

The problem was leakage of product under the base plate in trickles suggesting there is a pinhole in the steel annular plate. It was nearly impossible to remove the hardened product and consequently the location of the pinhole is impossible to locate.

APPLICATION SITUATION

Old storage tank being brought back into service due to client demands, the company needed to refurbish the tanks with health & safety in mind. The tanks hold neutral sodium silicate and the old product has solidified in the bottom of the tank, removal was not cost effective.

APPLICATION METHOD

The steel annular plate was abraded manually to give a rough finish, and the concrete receive the same treatment to remove any debris and contamination. Belzona 2911 was applied between the base plate and plinth and allowed to dry. Belzona 2211 was applied into the gap to provide a seal and prevent further product leakage. Belzona 3921 and Belzona 3931 were applied to condition the annular plate, followed by two coats of Belzona 3131 to finish. The application was completed in accordance with Belzona System Leaflet GSS-3.

BELZONA FACTS

Belzona offered a leak sealing solution to the client and a flexible protection system for the interface between the annular plate and concrete plinth. The cost savings here are huge as they could not use this tank for H&S reasons due to product leakage into the bunded area. A new tank would have been the only answer.

INDUSTRY

General Industry

LOCATION

Chemical Company, Warrington

APPLICATION DATE

October 2019

PRODUCTS

Belzona 2911 (QD Conditioner)
Belzona 2211 (MP Hi-Build Elastomer)
Belzona 3921 (GSC Conditioner)
Belzona 3931 (WG Conditioner)
Belzona 3131 (WG Membrane)

SUBSTRATE

Steel & Concrete.

PHOTOS

1. Showing annular plate / concrete plinth leakage and corrosion
2. Shows solidified product in the base of the tank
3. Application of conditioners
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA