

RENOVATION OF A LIQUID CYCLONE HEAD WITH BELZONA

ID: 8148



PROBLEM

The piece of equipment was badly damaged by erosion caused by the paper paste which is very abrasive.

APPLICATION SITUATION

Inside of a liquid cyclone head for paper

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet VPF-01 and VPF-02. The corroded metal structure was blasted back to bare metal using grit blasting and the eroded areas were rebuilt applying Belzona 1814 with spatula. Belzona 1321 was applied with brush to protect against future erosion/corrosion.

BELZONA FACTS

The repair cost was near to the replacement cost but with the Belzona 1321 coating, the equipment's expected service life is up to three times longer.

INDUSTRY

Pulp & Paper

LOCATION

Paper mill in France

APPLICATION DATE

2019

PRODUCTS

Belzona 1814

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. Liquid cyclone head badly damaged
2. After grit blasting
3. After Belzona 1814 application
4. Completely renovated after Belzona 1321 application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

