

BELZONA REPAIR STRAINERS

ID: 8180



PROBLEM

Strainers badly eroded

APPLICATION SITUATION

Fishing vessel strainers

APPLICATION METHOD

Application was carried out according to the system leaflet SOS-1 & SOS-2

BELZONA FACTS

These strainers are very badly damaged and is very costly to repair or manufacture new ones. The only economical way to repair then is with Belzona.

INDUSTRY

Marine

LOCATION

Namibia

APPLICATION DATE

14 October 2019

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1321 (Ceramic S-metal)
Belzona 5811 (Immersion grade)

SUBSTRATE

Cast iron

PHOTOS

1. Strainer badly corroded
2. Strainer Flange
3. After grid blast
4. Final product done with Belzona 1111 and Belzona 1321, with Belzona 5811 on the outside.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

