

BELZONA REPAIR ON A THRUSTER BODY

ID: 8182



PROBLEM

Heavy wear on body of thruster due to sea water.

APPLICATION SITUATION

Thruster body repair.

APPLICATION METHOD

Application was carried out according to the Belzona Know-How system leaflet SOS-2

BELZONA FACTS

Belzona offered a repair system that was economically competitive and could protect against future wear.

INDUSTRY

Marine

LOCATION

Namibia

APPLICATION DATE

2020-03-02.

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Steel

PHOTOS

1. Before 2. after repair with Belzona 1111 and Belzona 1321.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

