

ACID MIXING TANK DRIP MITIGATED WITH BELZONA

ID: 8183



PROBLEM

Regular dripping from the acid mixing tank was causing severe degradation to the concrete at the feet of the tank. The acid mixture had been absorbed into the concrete, threatening to damage the supporting structure.

APPLICATION SITUATION

Repair and protection of a concrete containment area in a brewery.

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet FPA-3. The concrete was washed repeatedly with Belzona 9111 (Cleaner Degreaser) to remove acid contamination from the concrete. The concrete surface was rebuilt using Belzona 4131 (Magma-Screed) and protected from further chemical attack with Belzona 4311 (Magma CR1).

BELZONA FACTS

The application was completed within 1 day, offering a significant reduction in downtime when compared with laying new concrete. The high chemical resistance of the Belzona 4311 (Magma CR1) top coat offers excellent resistance to the acid mixture, preventing further damage and reducing the future maintenance requirements.

INDUSTRY

Food & Drink

LOCATION

South Africa

APPLICATION DATE

February 2020

PRODUCTS

Belzona 9111 (Cleaner Degreaser)
Belzona 4911 (Magma TX Conditioner)
Belzona 4131 (Magma-Screed)
Belzona 4311 (Magma CR1)

SUBSTRATE

Concrete

PHOTOS

1. Original condition of damaged concrete 2. Post cleaning, surface primer being applied 3. Concrete rebuilding 4. Complete application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.