

BELZONA REPAIRS A THRUSTER

ID: 8184



PROBLEM

Heavily pitted and corroded on the out side of the thruster housing which would be costly and time-consuming to repair.

APPLICATION SITUATION

Stern Thruster for sea going vessel has a large degree of pitting due to erosion-corrosion by sea water.

APPLICATION METHOD

Application was carried out according to the KHIA Leaflet SOS-1.

BELZONA FACTS

This is very costly to replace and also to weld up and grind down to size. Belzona is a very cost effective way to repair and protect.

INDUSTRY

Marine

LOCATION

Namibia

APPLICATION DATE

2020-03-04

PRODUCTS

Belzona 1111 (Super metal)

Belzona 1321 (Ceramic S-metal)

SUBSTRATE

Steel

PHOTOS

1. Pitted Housing 2. After grid blast 3. after applying Belzona 1111 4. Final coat Belzona 1321

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

