

BELZONA 5892 PROTECTS CEMENT PLANT WALLS

ID: 8198



PROBLEM

The temperature in the furnace bag filters has caused corrosion of the bag filter walls.

APPLICATION SITUATION

Damaged walls of the furnace bag filters on a Cement plant.

APPLICATION METHOD

Abrasive grit blasting, dust removal of wall surfaces and bag filter sieves. Then a Belzona 5892 two coat system was applied.

BELZONA FACTS

A cost effective solution for the customer using Belzona 5892 was a key driver however the back up service and support from the local distributor was key to the client making the decision to use Belzona.

INDUSTRY

Cement

LOCATION

Poland

APPLICATION DATE

2019

PRODUCTS

Belzona 5892

SUBSTRATE

Steel

PHOTOS

1. Oven bag filter before protection
2. Grit blasting filter surface
3. First Layer of Belzona 5892
4. Oven bag filter after 2nd Layer of Belzona 5892

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA®