

DAIRY FARM WASH STATION PROTECTED WITH BELZONA 4181

ID: 8202



PROBLEM

Unsealing of the joints in the dairy plant wash station causes floor destruction.

APPLICATION SITUATION

The floor in a wash station of a dairy plant had a number of issues due to the unsealing of joints.

APPLICATION METHOD

The Application was completed in accordance with Belzona System Leaflet FPA-01. Removal of damaged concrete and leveling the pump work area. Belzona 4111 applied around the damaged drain area. Belzona 4181 used to provide a chemically resistance to the floor area then post cured by heating the Belzona 4181 for 4 hours.

BELZONA FACTS

Belzona have an excellent chemical resistant range suitable for application on concrete.

INDUSTRY

Food & Drink

LOCATION

Poland

APPLICATION DATE

2019

PRODUCTS

Belzona 4111 (Magma- Quartz)
Belzona 4181 (AHR Magma Quartz)
Belzona 4911

SUBSTRATE

Concrete

PHOTOS

1. Damaged chemically resistant floors
2. Belzona 4111 around the drain.
3. Application of Belzona 4181
4. Complete Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

