

PAPER & PULP PLANT TANK REPAIRED WITH BELZONA 5892

ID: 8203



PROBLEM

Internal of the condensate tank at the paper & pulp plant was suffering from corrosion.

APPLICATION SITUATION

Condensate tank suffering from corrosion.

APPLICATION METHOD

Substrate grit blasted to surface cleanliness (Sa21/2). Followed a profile check for the min surface roughness of 75 microns. Degreasing surfaces with Belzona degreaser 9121 and applied Belzona 5892 in a two coat system. The application was completed in accordance with Belzona System Leaflet TCC-05.

BELZONA FACTS

Belzona have proven solutions for the paper & pulp industry and used the local distributor for back up service and support.

INDUSTRY

Pulp & Paper

LOCATION

Poland

APPLICATION DATE

2019

PRODUCTS

Belzona 5892 Belzona 9121 (Thinners)

SUBSTRATE

Steel

PHOTOS

Condensation Tank Application of Belzona 5892
Belzona 5892 2nd layer
Application Complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

