

SEALING A TRANSFORMER USING BELZONA

ID: 8251



PROBLEM

Various places from which oil has escaped due to a defective seal.

APPLICATION SITUATION

Transformer connections

APPLICATION METHOD

The surface would be sanded and cleaned mechanically, the exiting areas were sealed with Belzona 1212. In addition, the entire joint was sealed with Belzona 1161 and overcoated with Belzona 5831. The application was completed in accordance with Belzona System Leaflet GSS-08.

BELZONA FACTS

As an alternative repair, there was only a complete disassembly of the transformer. This work would have taken several days and would have been many times more expensive than the Belzona solution. Thanks to Belzona, the customer now has a long-term & cost-effective solution.

INDUSTRY

Oil & Gas

LOCATION

Schweiz

APPLICATION DATE

August 2019

PRODUCTS

Belzona 1212
Belzona 1161 (UW-Metal)
Belzona 5831 (St-Barrier)

SUBSTRATE

Steel

PHOTOS

1. Assessment of the leak places
2. Machine grinding and cleaning the surface, and seal with Belzona 1212
3. Connection and screw heads with Belzona 1161
4. Screws and connection with Belzona 5831 seal

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

