


BELZONA KEEPS DECKING SAFE

ID: 827



PROBLEM

Slipping hazard, particularly when wet. Also wear on top surface.

APPLICATION SITUATION

Grooved timber decking

APPLICATION METHOD

The application was carried out using a modified version of the Belzona Know-How System Leaflet FPA-8. The Belzona® 5811 was mixed with 50% of Belzona® 9211.

BELZONA FACTS

Following this initial area being treated a water spillage occurred half on the decking and half on the Belzona Grip System. It was noted that the timber decked area was extremely slippery and hazardous whereas the area covered with the Belzona gave excellent grip properties even when soaked with water. The use of Belzona has become a standard procedure at this site with a further large area being treated in 2007.

INDUSTRY

Buildings & Structures

LOCATION

Holiday Village, Penrith

APPLICATION DATE

2002

PRODUCTS

Belzona 5811 (Immersion Grade)

Belzona 9211 (Supergrip Aggregate)

SUBSTRATE

Wood

PHOTOS

1. Slippage problem area.
2. Belzona grip system was mixed and piped using polyethylene bag, and then spread with an applicator. Further aggregate was then spread over the area.
3. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

