

BELZONA BONDS PLATES WITH MAGNET CONSTRUCTION SUPPORT.

ID: 8293



PROBLEM

The tank was damaged by corrosion from aggressive residual water at crude oil production process. Because the customer needed very quickly repair he made decision to repair only damaged parts of the tank.

APPLICATION SITUATION

Chemical corrosion leads to tank wall damage.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System leaflet TCC-1. The surfaces (tank and plates) were abrasive blasted to prepare the area and Belzona 1111 was applied directly onto the prepared surface with a spatula.

BELZONA FACTS

This customer has perfect experiences with Belzona repairs and protection. Our suggest of this reparation offered to save him a lot of time without using some expensive tools. This was not our first time, when we have utilized this magnet construction to keep plates on the right place with sufficient pressure.

INDUSTRY

Chemical & Petrochemical

LOCATION

Crude oil production plant in Slovakia.

APPLICATION DATE

2020

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Tank was damaged by corrosion from aggressive residual water
2. Chemical corrosion leads to tank wall damage
3. Belzona 1111 was applied directly onto the prepared surface
4. Magnet construction keeps plate on the right place with sufficient pressure.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

