

BELZONA 1381 TANK PROTECTION

ID: 8301



PROBLEM

The problem was an abrasion from water (with salt - CaCl_2 , CaSO_4 , CaOH , MgOH ...) + silica sand. They missing 3,5 mm of the wall (at the bottom of the tank) after 4 years of production.

APPLICATION SITUATION

This customer uses 3 tanks with a fluid flow mix. 2 tanks are bigger, last one is smaller.

APPLICATION METHOD

These tanks were blasted and cleaned. Two coats of Belzona 1381 were applied by spraying. The application was done in accordance with Belzona System Leaflet TCC-5.

BELZONA FACTS

The customer was looking for some good anti abrasive coating some longer time. In the end we offered him Belzona 1381. First one was done in 2019. After one year (because Belzona 1381 shows itself to be perfect protection, no damage on the surface) the customer wanted to coat another 2 tanks.

INDUSTRY

Fluid Flow

LOCATION

Slovakia

APPLICATION DATE

2019, 2020

PRODUCTS

Firstly we have considered going with Belzona 1321/1331 but then this customer specified the temperature - close to 60°C so we offered him Belzona 1381.

SUBSTRATE

Steel

PHOTOS

1. Two tanks are bigger
2. Fluid flow mix
3. Tank was blasted and cleaned
4. Second layer of Belzona 1381

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA®